


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350℃, 50 Watt max . and use a pencil tip.
- 4. Put tip to wire in solder cup.
- 5. After 1 second bring in solder.
- 6. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 7. Remove soldering iron.
- 8. Wait until solder gets rigid again.
- 9. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



_												
	ED OR AAY NOT / WITHOUT CONEC GMbH	BY HAND					tolerance			\Box	scale: 3:1	
									material: SEE SHEET 1			
									dim.	in mm		
	E COPIED AND MAY PARTY WI	DRAWING						date	nam	ne	title:	
	AND AND PAR						drawn	08.07.13	Lehmen	kühler	RECOMMENDED PANEL CUT-OUT	
	AY NOT BE CAN WAY, AN A THIRD PASION. COPYRIGHT						appd.	11.07.13	Fiscl	her	D-SUB FEMALE 9pos. SOLDER CUP	
	NON TO S	GAD					norm				with threaded lock and 4-40 UNC stud bolt	
₩ B	₹ 5 5 2 d	TH.					d-old				dwg no: DIN-	
	WING CED II D ON PERM	 -					_	45 =		8	15K1 \ 1226	
	DRA ODU SSE TEN	NOT	а	Original						ſ "	15K1A1336	
	THIS DRAWIN REPRODUCED BE PASSED C WRITTEN PER OWNERSHIP	8	rev.	description	date	name	•		7 1 1 1		part no: SEE SHEET 1	
			n		<u> </u>						B A	