

PIC16F716 Silicon Errata and Data Sheet Clarification

The PIC16F716 device that you have received conforms functionally to the current Device Data Sheet (DS41206**B**), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in Table 1. The silicon issues are summarized in Table 2.

The errata described in this document will be addressed in future revisions of the PIC16F716 silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of Table 2 apply to the current silicon revision (A6).

Data Sheet clarifications and corrections start on page 4, following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with MPLAB ICD 2, MPLAB ICD 3, PICkit TM 2 or PICkit TM 3:

- Using the appropriate interface, connect the device to the MPLAB ICD 2 programmer/ debugger, PICkit™ 2 or PICkit™ 3.
- 2. From the main menu in MPLAB IDE, select <u>Configure>Select Device</u>, and then select the target part number in the dialog box.
- Select the MPLAB hardware tool (<u>Programmer>Select Tool</u>).
- Perform a "Connect" operation to the device (<u>Programmer>Connect</u>). Depending on the development tool used, the part number and Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The Device ID values for the various devices and silicon revisions are shown in Table 1.

TABLE 1: SILICON DEVREY VALUES

Part Number	Device ID ⁽¹⁾	Revision ID for Silicon Revision ⁽²⁾				
Part Number	Device ID.	A4	A5	A6		
PIC16F716	01 0001 010x xxxx	4	5	5		

Note 1: The device and revision data is stored in the Device ID located at 2006h in program memory.

2: Refer to the "PIC16F716 Flash Programming Specification" (DS40245) for detailed information.

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item	Issue Summary	Affected Revisions ⁽¹⁾		
Wodule	reature	Number Issue Sum		A4	A5	A6
Programming	In-Circuit Serial Programming™ (ICSP™)	1.	Oscillator affects programming.	Х		
ECCP	Software Interrupt mode/ Special Event Trigger	2.	RB3 cannot drive high in these ECCP modes.	Х	Х	Х
ECCP	PWM	3.	Duty cycle may be extended by one oscillator period.	Х	Х	Х

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

Silicon Errata Issues

Note:

This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (A6).

1. Module: Silicon - Programming

The oscillator circuitry may prevent proper initialization of the Programming mode when the part is programmed in-circuit.

Work around

Tie the OSC1/EXTCLK pin (pin 16 of 18-pin package or pin 18 of 20-pin package) to ground to disable the oscillator during In-Circuit Serial Programming $^{\text{TM}}$.

Affected Silicon Revisions

A4	A5	A6			
Χ					

2. Module: ECCP

The ECCP module will override pin data of the RB3/CCP1 pin when operating in Software Interrupt mode (CCP1M = 0xA) or Special Event Trigger mode (CCP1M = 0xB). The RB3/CCP1 pin can be used as a general purpose input by setting the TRISB3 bit. However, if the pin is configured as an output, the ECCP module will always drive the pin low.

This affects all released versions of silicon.

Work around

None.

Affected Silicon Revisions

A4	A5	A6			
Χ	Χ	Χ			

3. Module: ECCP

The falling edge of the PWM waveform may be extended by one system oscillator period if the falling edge coincides with a write to the PORTB register.

This affects all released versions of silicon.

Work around

Test the PWM pin status in software and postpone writing to PORTB until the pin is low.

Affected Silicon Revisions

A4	A5	A6			
Χ	Χ	Χ			

Data Sheet Clarifications

The following typographical corrections and clarifications are to be noted for the latest version of the device data sheet (DS41206**B**):


Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

1. Module: Oscillator Configuration

In Figure 9-3, revise the second line of recommended values as follows:

10 k $\Omega \le Rext \le 100 \ k\Omega$ (VDD < 3.0V)

FIGURE 9-3: RC OSCILLATOR MODE



Recommended values:

- $3 \text{ K}\Omega \leq \text{REXT} \leq 100 \text{ k}\Omega \text{ (VDD} \geq 3.0 \text{V)}$
- 10 $K\Omega \leq Rext \leq$ 100 $k\Omega$ (VDD < 3.0V)
- CEXT > 20 pF

2. Module: Electrical Characteristics

In Section 12.4, "DC Characteristics: PIC16F716 (Industrial, Extended)", changes to parameter numbers D033A and D042B are shown in bold and italics below.

12.4 DC Characteristics: PIC16FXXXX (Industrial, Extended)

DC CHAR	ACTEDIS	TICS	Standard Operating Conditions (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \le \text{TA} \le +85^{\circ}\text{C}$ for industrial $-40^{\circ}\text{C} \le \text{TA} \le +125^{\circ}\text{C}$ for extended					
DO CHAR	ACTERIO	1103	Section 12.	.1 "ĎC CI	naracteristic	s: PIC16	in DC specification F716 (Industrial, Extended)" and F716 (Industrial, Extended)"	
Param No.	Sym	Characteristic	Min	Typ†	Max	Units	Conditions	
	VIL	Input Low Voltage						
		I/O ports						
D030		with TTL buffer	Vss	_	0.8V	V	$4.5V \le VDD \le 5.5V$	
D030A			Vss	_	0.15VDD	V	otherwise	
D031		with Schmitt Trigger buffer	Vss	_	0.2VDD	V		
D032		MCLR, OSC1 (in RC mode)	Vss	_	0.2VDD	V		
D033		OSC1 (in HS mode)	Vss	_	0.3VDD	V	(Note 1)	
D033A	\ /	OSC1 (in XT and LP modes)	Vss	_	0.3	V		
	VIH	Input High Voltage I/O ports	1				T	
D040		with TTL buffer	2.0	_	1/00	V	4.5V ≤ VDD ≤ 5.5V	
D040 D040A		with TTL builer	0.25 VDD		VDD VDD	V	4.5 v ≤ vDD ≤ 5.5 v otherwise	
D040A			+ 0.8V	_	VDD	V	otherwise	
D041		with Schmitt Trigger buffer	0.8 VDD	_	Vpp	V	For entire VDD range	
D041		MCLR	0.8 VDD	_	VDD	v	To chare vob range	
D042A		OSC1 (HS)	0.7 VDD	_	VDD	v	(Note 1)	
D042B		OSC1 (XT and LP modes)	1.6	_	VDD	v	(Note 1)	
D043		OSC1 (in RC mode)	0.9 VDD	_	VDD	V		
	IIL	Input Leakage Current ^{(2), (3)}					L	
D060	"L	I/O ports			±1	μА	Vss ≤ VPIN ≤ VDD, Pin at	
D000		" o porto			Ξ.	μιν	high-impedance	
D061		MCLR, RA4/T0CKI	_	_	±5	μА	Vss ≤ VPIN ≤ VDD	
D063		OSC1/CLKIN	_	_	±5	μA	Vss ≤ VPIN ≤ VDD, XT, HS and LP Oscillator modes	
D070	IPURB	PORTB weak pull-up current	50	250	400	μА	VDD = 5V, VPIN = VSS	
	Vol	Output Low Voltage						
D080		I/O ports	_	_	0.6	V	IOL = 8.5 mA, VDD = 4.5V, -40°C to +85°C	
			_	_	0.6	V	IOL = 7.0 mA, VDD = 4.5V, -40°C to +125°C	
D083		OSC2/CLKOUT (RC Oscillator mode)	_	_	0.6	V	IOL = 1.6 mA, VDD = 4.5V, -40°C to +85°C	
			_	1	0.6	V	IOL = 1.2 mA, VDD = 4.5V, -40°C to +125°C	
	Vон	Output High Voltage						
D090		I/O ports ⁽³⁾	VDD - 0.7	_	_	V	IOH = -3.0 mA, VDD = 4.5V, -40°C to +85°C	
			VDD - 0.7	_	_	V	IOH = -2.5 mA, VDD = 4.5V, -40°C to +125°C	
D092		OSC2/CLKOUT (RC Oscillator mode)	VDD - 0.7	_	_	V	IOH = -1.3 mA, VDD = 4.5V, -40°C to +85°C	
			VDD - 0.7			V	IOH = -1.0 mA, VDD = 4.5V, -40°C to +125°C	
D150*	Vod	Open-Drain High Voltage			8.5	V	RA4 pin	
		Capacitive Loading Specs on Output	Pins					
D100	COSC2	OSC2/CLKOUT pin	_	-	15	pF	In XT, HS and LP modes when external clock is used to drive OSC1.	
D101	Сю	All I/O pins and OSC2 (in RC mode)	_	_	50	pF		

These parameters are characterized but not tested.

Data in "Typ" column is at 5V, 25°C unless otherwise stated. These parameters are for design guidance only and are not tested. In RC Oscillator mode, the OSC1/CLKIN pin is a Schmitt Trigger input. It is not recommended that the PIC® microcontroller be driven Note 1: with external clock in RC mode.

The leakage current on the MCLR/VPP pin is strongly dependent on the applied voltage level. The specified levels represent normal operating conditions. Higher leakage current may be measured at different input voltages. Negative current is defined as current sourced by the pin.

3. Module: Interrupts

Legend:

R = Readable bit

The IOCB register is not used on this device. The interrupt-on-change feature will automatically be enabled for any RB<7:4> configured as an input. See Section 3.2 "PORTB and the TRISB Register" in the data sheet (DS41206B) for more information.

REGISTER 2-3: INTCON: INTERRUPT CONTROL REGISTER

W = Writable bit

R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-0	R/W-x
GIE	PEIE	T0IE	INTE	RBIE	T0IF ⁽¹⁾	INTF	RBIF
bit 7							bit 0

U = Unimplemented bit, read as '0'

			'	
-n = Value at P	OR	'1' = Bit is set	'0' = Bit is cleared	x = Bit is unknown
bit 7		nterrupt Enable bit		
	0 = Disables			
bit 6	1 = Enables a	eral Interrupt Enable bit Ill unmasked peripheral inter all peripheral interrupts	rupts	
bit 5	1 = Enables t	Overflow Interrupt Enable bi ne Timer0 interrupt he Timer0 interrupt	t	
bit 4	1 = Enables t	T External Interrupt Enable I ne RB0/INT external interrup he RB0/INT external interrup	t	
bit 3	1 = Enables t	B Change Interrupt Enable bine PORTB change interrupt the PORTB change interrupt		
bit 2	1 = TMR0 reg	Overflow Interrupt Flag bit ⁽¹⁾ ister has overflowed (must b ister did not overflow		
bit 1	1 = The RB0/	T External Interrupt Flag bit INT external interrupt occurr INT external interrupt did not	ed (must be cleared in softwa	re)
bit 0		B Change Interrupt Flag bit east one of the PORTB gene	ral purpose I/O pins changed	state (must be cleared in soft-
	0 = None of th	ne PORTB general purpose	I/O pins have changed state	

Note 1: T0IF bit is set when Timer0 rolls over. Timer0 is unchanged on Reset and should be initialized before clearing T0IF bit.

4. Module: ADC

Corrected values for the acquisition time example for the 8-bit ADC used by this device are shown below.

EQUATION 7-1: ACQUISITION TIME EXAMPLE

Assumptions: Temperature = 50° C and external impedance of $10k\Omega 5.0V VDD$

$$TACQ = Amplifier Settling Time + Hold Capacitor Charging Time + Temperature Coefficient$$

= $TAMP + TC + TCOFF$
= $5 \mu s + TC + [(Temperature - 25°C)(0.05\mu s/°C)]$

The value for TC can be approximated with the following equations:

$$V_{APPLIED} \left(1 - \frac{1}{511} \right) = V_{CHOLD}$$
 ;[1] VCHOLD charged to within 1/2 lsb

$$V_{APPLIED}\left(1 - e^{\frac{-T_C}{RC}}\right) = V_{CHOLD}$$
 ;[2] V_{CHOLD} charge response to $V_{APPLIED}$

$$V_{APPLIED}\left(1 - e^{\frac{-Tc}{RC}}\right) = V_{APPLIED}\left(1 - \frac{1}{511}\right)$$
 ; combining [1] and [2]

Solving for TC:

$$TC = -C_{HOLD}(RIC + RSS + RS) \ln(1/511)$$

$$= -10pF(1k\Omega + 7k\Omega + 10k\Omega) \ln(0.0019569)$$

$$= 1.12 \mu s$$

Therefore:

$$TACQ = 5MS + 1.12MS + [(50^{\circ}C - 25^{\circ}C)(0.05MS/^{\circ}C)]$$

= 7.37\mu s

5. Module: Electrical Characteristics

In Section 12.0, "Electrical Characteristics", change (in bold):

From: Voltage on RA4 with respect to Vss 0V to

+8.5V

To: Voltage on RA4 with respect to Vss

-0.3V to +8.5V

APPENDIX A: REVISION HISTORY

Rev. A Document (2/19/04)

First revision of this document.

Rev. B Document (7/12/04)

Changes made to parameter numbers D033A and D042B in Section 12.4, "DC Characteristics: PIC16F716 (Industrial, Extended)".

Rev. C Document (3/28/07)

Changes made to the data sheet revision referenced (DS41206B), emphasis added in Figure 9-3, "RC Oscillator Mode", to the second recommended value, removed note 1 in register 2-3, "INTCON: Interrupt Control Register", and adjusted values in Equation 7-1 "Acquisition Time Example".

Rev. D Document (8/22/07)

Added Module 5: Electrical Characteristics (add -0.3V to "Voltage on RA4").

Rev. E Document (4/02/08)

Added Module 2: ECCP on first page.

Rev. F Document (5/10)

Updated Errata to new format.

Added Module 3:ECCP. Added Tables 1 and 2.

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our
 knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data
 Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC³² logo, rfPIC and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Octopus, Omniscient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICtail, REAL ICE, rfLAB, Select Mode, Total Endurance, TSHARC, UniWinDriver, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2010, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

Printed on recycled paper.

ISBN: 978-1-60932-222-9

QUALITY MANAGEMENT SYSTEM

CERTIFIED BY DNV

ISO/TS 16949:2002

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office 2355 West Chandler Blvd.

Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277

Technical Support:

http://support.microchip.com

Web Address: www.microchip.com

Atlanta

Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455

Boston

Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088

Chicago Itasca. IL

Tel: 630-285-0071 Fax: 630-285-0075

Cleveland

Independence, OH Tel: 216-447-0464 Fax: 216-447-0643

Dallas

Addison, TX Tel: 972-818-7423 Fax: 972-818-2924

Detroit

Farmington Hills, MI Tel: 248-538-2250 Fax: 248-538-2260

Kokomo

Kokomo, IN Tel: 765-864-8360 Fax: 765-864-8387

Los Angeles

Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608

Santa Clara

Santa Clara, CA Tel: 408-961-6444 Fax: 408-961-6445

Toronto

Mississauga, Ontario,

Canada

Tel: 905-673-0699 Fax: 905-673-6509 ASIA/PACIFIC

Asia Pacific Office Suites 3707-14, 37th Floor Tower 6, The Gateway Harbour City, Kowloon

Hong Kong Tel: 852-2401-1200

Fax: 852-2401-3431

Australia - Sydney

Tel: 61-2-9868-6733 Fax: 61-2-9868-6755

China - Beijing

Tel: 86-10-8528-2100 Fax: 86-10-8528-2104

China - Chengdu

Tel: 86-28-8665-5511 Fax: 86-28-8665-7889

China - Chongqing

Tel: 86-23-8980-9588 Fax: 86-23-8980-9500

China - Hong Kong SAR

Tel: 852-2401-1200 Fax: 852-2401-3431

China - Nanjing

Tel: 86-25-8473-2460 Fax: 86-25-8473-2470

China - Qingdao

Tel: 86-532-8502-7355 Fax: 86-532-8502-7205

China - Shanghai

Tel: 86-21-5407-5533 Fax: 86-21-5407-5066

China - Shenyang

Tel: 86-24-2334-2829 Fax: 86-24-2334-2393

China - Shenzhen

Tel: 86-755-8203-2660 Fax: 86-755-8203-1760

China - Wuhan

Tel: 86-27-5980-5300 Fax: 86-27-5980-5118

China - Xian

Tel: 86-29-8833-7252 Fax: 86-29-8833-7256

China - Xiamen

Tel: 86-592-2388138 Fax: 86-592-2388130

China - Zhuhai

Tel: 86-756-3210040 Fax: 86-756-3210049 ASIA/PACIFIC

India - Bangalore

Tel: 91-80-3090-4444 Fax: 91-80-3090-4123

India - New Delhi

Tel: 91-11-4160-8631 Fax: 91-11-4160-8632

India - Pune

Tel: 91-20-2566-1512 Fax: 91-20-2566-1513

Japan - Yokohama

Tel: 81-45-471- 6166 Fax: 81-45-471-6122

Korea - Daegu

Tel: 82-53-744-4301 Fax: 82-53-744-4302

Korea - Seoul

Tel: 82-2-554-7200 Fax: 82-2-558-5932 or 82-2-558-5934

Malaysia - Kuala Lumpur

Tel: 60-3-6201-9857 Fax: 60-3-6201-9859

Malaysia - Penang

Tel: 60-4-227-8870 Fax: 60-4-227-4068

Philippines - Manila

Tel: 63-2-634-9065 Fax: 63-2-634-9069

Singapore

Tel: 65-6334-8870 Fax: 65-6334-8850

Taiwan - Hsin Chu

Tel: 886-3-6578-300 Fax: 886-3-6578-370

Taiwan - Kaohsiung

Tel: 886-7-536-4818 Fax: 886-7-536-4803

Taiwan - Taipei

Tel: 886-2-2500-6610 Fax: 886-2-2508-0102

Thailand - Bangkok

Tel: 66-2-694-1351 Fax: 66-2-694-1350 EUROPE

Austria - Wels

Tel: 43-7242-2244-39 Fax: 43-7242-2244-393

Denmark - Copenhagen

Tel: 45-4450-2828 Fax: 45-4485-2829

France - Paris

Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79

Germany - Munich

Tel: 49-89-627-144-0 Fax: 49-89-627-144-44

Italy - Milan

Tel: 39-0331-742611 Fax: 39-0331-466781

Netherlands - Drunen

Tel: 31-416-690399 Fax: 31-416-690340

Spain - Madrid

Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 **UK - Wokingham**

Tel: 44-118-921-5869 Fax: 44-118-921-5820

01/05/10